

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B1

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 9 Line 9 Fig/Table# Subclause 6.3.2.1.1.1

The header for Table 6a should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Syntax" with "Name"

Replace "Size" with "Length (bit)"

Replace "Notes" with "Description"

Remove the word "bit" and "bits" from the table entries in the second column

GroupResolution

Decision of Group: Principle

Replace "Syntax" with "Name"

Replace "Size" with "Length (bit)"

Replace "Notes" with "Description"

Remove the word "bit" and "bits" from the table entries in the second column.

Remove the rows including "Relay MAC Header() {" and "} ".

Reason for Group's Decision/Resolution

Commenter missed one part of the table that also needs to be updated

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B2

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial

Part of Dis Satisfied

Page 15

Line 27

Fig/Table#

Subclause 6.3.2.1.2.2.1

The header for Table 18d should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Length" with "Length (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B3

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 16 Line 35 Fig/Table# Subclause 6.3.2.1.2.2.2

The header for Table 18e should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Syntax" with "Name"
Replace "Size" with "Length (bit)"
Replace "Notes" with "Description"
Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Principle

Replace "Syntax" with "Name".
Replace "Size" with "Length (bit)".
Replace "Notes" with "Description".
Remove the word "bit" or "bits" from the table entries in the second column.
Delete " MAC Header () }" and "} " (line 51, page 17).

Reason for Group's Decision/Resolution

Commenter missed one part of the table that also needs to be updated

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B4

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 18 Line 43 Fig/Table# Subclause 6.3.2.1.2.2.2.3

The header for Table 18f should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Length (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B5

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 19 Line 36 Fig/Table# Subclause 6.3.2.1.2.2.2.4

The header for Table 18g should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Length (bits)" with "Length (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B6

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 20 Line 31 Fig/Table# Subclause 6.3.2.1.2.2.2.5

The header for Table 18h should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Length" with "Length (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B7

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 21 Line 27 Fig/Table# Subclause 6.3.2.1.2.2.2.6

The header for Table 18i should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Length" with "Length (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B8

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 22 Line 35 Fig/Table# Subclause 6.3.2.1.2.2.2.7

The header for Table 18j should match the other header fields table headers in Section 6.3.2.1, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Length (bits)" with "Length (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B9

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 23 Line 27 Fig/Table# Subclause 6.3.2.2.8.1

The header for Table 37a should match the other header fields table headers in Section 6.3.2.2, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B10

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 24 Line 8 Fig/Table# Subclause 6.3.2.2.8.2

The header for Table 37b should match the other subheader format table headers in Section 6.3.2.2, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B11

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 24 Line 35 Fig/Table# Subclause 6.3.2.2.8.3

The header for Table 37c should match the other subheader format table headers in Section 6.3.2.2, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B12

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 25 Line 10 Fig/Table# Subclause 6.3.2.2.8.4

The header for Table 37d should match the other subheader format table headers in Section 6.3.2.2, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B13

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 38 Line 37 Fig/Table# Subclause 6.3.2.3.51

The header for Table 154 should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B14

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 40 Line 16 Fig/Table# Subclause 6.3.2.3.60

The header for Table 165a should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B15

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 41 Line 11 Fig/Table# Subclause 6.3.2.3.61

The header for Table 165b should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B16

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 45 Line 20 Fig/Table# Subclause 6.3.2.3.62

The header for Table 165c should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B17

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 47 Line 48 Fig/Table# Subclause 6.3.2.3.63

The header for Table 165d should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
The table entries in the first row of the table should be in bold text and centered in the cell.
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B18

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 50 Line 10 Fig/Table# Subclause 6.3.2.3.64

The header for Table 165e should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B19

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 51 Line 23 Fig/Table# Subclause 6.3.2.3.65.1

The header for Table 165f should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B20

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 52 Line 8 Fig/Table# Subclause 6.3.2.3.65.2

The header for Table 165g should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B21

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 53 Line 7 Fig/Table# Subclause 6.3.2.3.66

The header for Table 165h should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B22

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 54 Line 11 Fig/Table# Subclause 6.3.2.3.67

The header for Table 165i should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B23

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 55 Line 6 Fig/Table# Subclause 6.3.2.3.68

The header for Table 165j should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B24

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 56 Line 4 Fig/Table# Subclause 6.3.2.3.69

The header for Table 165k should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B25

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 56 Line 29 Fig/Table# Subclause 6.3.2.3.70

The header for Table 165l should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B26

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 57 Line 11 Fig/Table# Subclause 6.3.2.3.71

The header for Table 165m should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B27

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 58 Line 17 Fig/Table# Subclause 6.3.2.3.72

The header for Table 165n should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B28

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 59 Line 18 Fig/Table# Subclause 6.3.2.3.73

The header for Table 165o should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B29

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 60 Line 7 Fig/Table# Subclause 6.3.2.3.73

The header for Table 165p should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B30

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 61 Line 7 Fig/Table# Subclause 6.3.2.3.74

The header for Table 165q should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B31

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 64 Line 11 Fig/Table# Subclause 6.3.2.3.75

The header for Table 165r should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B32

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 65 Line 10 Fig/Table# Subclause 6.3.2.3.76

The header for Table 165s should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B33

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 66 Line 8 Fig/Table# Subclause 6.3.2.3.77

The header for Table 165t should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B34

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 68 Line 11 Fig/Table# Subclause 6.3.2.3.78

The header for Table 165u should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B35

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 69 Line 9 Fig/Table# Subclause 6.3.2.3.79

The header for Table 165v should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B36

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 70 Line 8 Fig/Table# Subclause 6.3.2.3.80

The header for Table 165w should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B37

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 72 Line 35 Fig/Table# Subclause 6.3.2.3.80

The header for Table 165x should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B38

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 73 Line 29 Fig/Table# Subclause 6.3.2.3.80

The header for Table 165y should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B39

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 74 Line 6 Fig/Table# Subclause 6.3.2.3.80

The header for Table 165z should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B40

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 75 Line 4 Fig/Table# Subclause 6.3.2.3.80

The header for Table 165aa should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B41

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 76 Line 5 Fig/Table# Subclause 6.3.2.3.80

The header for Table 165ab should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B42

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 77 Line 14 Fig/Table# Subclause 6.3.2.3.81

The header for Table 165ac should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B43

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 78 Line 41 Fig/Table# Subclause 6.3.2.3.82

The header for Table 165ad should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B44

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 79 Line 25 Fig/Table# Subclause 6.3.2.3.83

The header for Table 165ae should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B45

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 80 Line 31 Fig/Table# Subclause 6.3.2.3.84

The header for Table 165af should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B46

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 81 Line 30 Fig/Table# Subclause 6.3.2.3.85

The header for Table 165ag should match the other message format table headers in Section 6.3.2.3, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B47

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 86 Line 5 Fig/Table# Subclause 6.3.4.2.2

The header for Table 169a should match the other message format table headers in Section 6.3.4.2, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B48

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 187 Line 11 Fig/Table# Subclause 7.2.2.4.5

The header for Table 206a should match the other table headers in Section 7.2.2.4, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size (bits)" with "Size (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B49

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 188 Line 11 Fig/Table# Subclause 7.2.2.4.6

The header for Table 206b should match the other table headers in Section 7.2.2.4, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size (bits)" with "Size (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B50

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 204 Line 8 Fig/Table# Subclause 8.4.4.10

The header for Table 317a should match the other table headers in Section 8.4.4, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size(bits)" with "Size (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B51

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 205 Line 6 Fig/Table# Subclause 8.4.4.10

The header for Table 317b should match the other table headers in Section 8.4.4, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size (bits)" with "Size (bit)"

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B52

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 207 Line 10 Fig/Table# Subclause 8.4.5.3

The header for Table 320 should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

GroupResolution

Decision of Group: Principle

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

Reason for Group's Decision/Resolution

Commenter missed one part of the table that also needs to be updated

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B53

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 211 Line 13 Fig/Table# Subclause 8.4.5.3.32

The header for Table 336a should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

If B30018 is accepted, this one does not require any action as B30018 will delete the section.

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B54

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 212 Line 7 Fig/Table# Subclause 8.4.5.3.33

The header for Table 336b should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B55

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 216 Line 7 Fig/Table# Subclause 8.4.5.4.30

The header for Table 465a should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B56

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 216 Line 31 Fig/Table# Subclause 8.4.5.4.31

The header for Table 465b should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B57

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 218 Line 24 Fig/Table# Subclause 8.4.5.4.32

The header for Table 465c should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

If B30018 is accepted, this one does not require any action as B30018 will delete the section.

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B58

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 219 Line 8 Fig/Table# Subclause 8.4.5.10

The header for Table 475a should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B59

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 220 Line 10 Fig/Table# Subclause 8.4.5.10.1

The header for Table 475b should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B60

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 221 Line 10 Fig/Table# Subclause 8.4.5.10.2

The header for Table 475d should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B61

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 223 Line 6 Fig/Table# Subclause 8.4.5.10.3

The header for Table 475e should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B62

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 224 Line 10 Fig/Table# Subclause 8.4.5.10.4

The header for Table 475f should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B63

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 226 Line 7 Fig/Table# Subclause 8.4.5.10.5

The header for Table 475g should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B64

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 227 Line 8 Fig/Table# Subclause 8.4.5.10.6

The header for Table 475h should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B65

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 228 Line 23 Fig/Table# Subclause 8.4.5.10.7

The header for Table 475i should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B66

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 229 Line 10 Fig/Table# Subclause 8.4.5.10.8

The header for Table 475j should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B67

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 230 Line 10 Fig/Table# Subclause 8.4.5.10.9

The header for Table 475k should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"

Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B68

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 230 Line 51 Fig/Table# Subclause 8.4.5.10.10

The header for Table 475l should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Harry Bims

Membership Status: Member

Date: 29-Dec-2008 4:23: 2 EST

Comment # B69

Document under Review:

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 232 Line 12 Fig/Table# Subclause 8.4.5.10.11

The header for Table 475m should match the other table headers in Section 8.4.5, as found in IEEE 802.16rev2.

Suggested Remedy

Replace "Size" with "Size (bit)"
Remove the word "bit" or "bits" from the table entries in the second column

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Roger Marks

Membership Status: Member

Date: 7-Jan-2009 1:50: 7 EST

Comment # B70

Document under Review:

Ballot ID: sb_16jR2

Comment Type General Part of Dis Satisfied Page 1 Line Fig/Table# Subclause

It is important to consider subclause 8.1.2 of the IEEE-SA Standards Board Operations

Manual<<http://standards.ieee.org/guides/opman/sect8.html#8.1>>, which says:

"Sponsor ballots of amendments and corrigenda shall also include access to the approved base standard and any approved amendments and corrigenda in order to provide sufficient information to the ballot group."

Suggested Remedy

Ensure that the ballot does not conclude until a recirculation has been conducted in which the _approved_ base standard is provided to the ballot group.

GroupResolution

Decision of Group: Principle

The procedures in the IEEE-SA Standards Board Operations Manual will be followed. The sponsor should communicate to the Sponsor Ballot Group, via the ballot cover letter, regarding the status of the amendment to base standard.

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions b) none needed

2009/09/06

IEEE 802.16-09/0001r3

Comment by: Daniel Lubar

Membership Status: Member

Date: 7-Jan-2009 10:55: 7 EST

Comment # B71

Document under Review:

Ballot ID: sb_16jR2

Comment Type General Part of Dis Satisfied Page ? Line 47 Fig/Table# Subclause

In Rev2 D8, despite the the fact that the Bibliography presented in Annex A is informative, I would urge that amendment j's TG work to update the references for the sake of quality/accuracy. A specific example is the reference to the 802.11 Standard [B28] which still points at the 1997 baseline. FYI the current 802.11 baseline is really a 2008 document. I would guess that some of the IETF & ITU documents are also in need of a refresh too.

Suggested Remedy

Undertake to refresh Annex A's document references.. Here is the refresh for [B28]..
Replace the existing text with at least the the 2007 baseline reference.. ie "[B28] IEEE Std 802.11(TM)-2007, IEEE Standard for Information Technology--Telecommunications and information exchange between systems--LANs and MANs--Specific requirements--Part 11: WLAN MAC and PHY Specifications"

GroupResolution

Decision of Group: Out of Scope

Response: This comment is out of scope of the ballot. The P802.16j Sponsor Ballot Group is not authorized to develop amendments to the underlying base standard.

Remedy: Since the base standard is currently under revision and in ballot, the comment has been forwarded to the Ballot Resolution Committee for that revision project. According to our understanding, that Committee has agreed to address the comment and will communicate its response to the voter. The P802.16j Sponsor Ballot Group will be provided with the base document and can therefore confirm any resultant changes.

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions b) none needed

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # B30001

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Technical Part of Dis Satisfied Page 210 Line 58 Fig/Table# 335b Subclause 8.4.5.3.32

There is a problem with the IE. Ns is not defined in table 335b. It is not clear how RS can locate the bursts to be forwarded by this IE.

Suggested Remedy

Define Ns in Table 335b.

GroupResolution

Decision of Group: Principle

remove "Ns and" at page 211, line 58

Reason for Group's Decision/Resolution

The parameter Ns should be removed. It is there in error.

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # B30002

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Technical Part of Dis Satisfied Page 105 Line 55 Fig/Table# 85b Subclause 6.3.9.9.2

In the figure, if neighborhood measurement report is not performed (Branch with "No" indication), the system enters "Perform operation configuration". However, for some RSs, there are optional stages, such as "tunnel establishment", "ip establishment", etc.

Suggested Remedy

Change as:

"Next stage as indicated by RNG_RSP ~~Perform operation parameter configuration~~"

GroupResolution

Decision of Group: Principle

"Next stage as indicated by RNG_RSP/REG-RSP ~~Perform operation parameter configuration~~" at page 106, line 25, figure 84b.

Reason for Group's Decision/Resolution

Correct the reference so the editors correct the right part of the draft/

Group's Notes

Editor's Notes

Editor's Actions a) done

Comment by:

Israfil Bahceci

Membership Status: Nonmember**Date:** 2009-01-07**Comment #** B30003**Document under Review:** P802.16j/D8**Ballot ID:** sb_16jR2**Comment** **Type** Technical **Part of Dis** **Satisfied** **Page** 107 **Line** 42 **Fig/Table#** **Subclause** 6.3.9.15

"If the measurement is not required, after registration RS shall directly go to the RS configuration phase skipping the neighbor station measurement report phase and second stage access selection phases."

However, even if measurement step is omitted, there may be a few intermediate stages that will not be omitted.

Suggested Remedy

Change as:

If the measurement is not required, after registration RS shall ~~directly go to the RS configuration phase skipping the neighbor station measurement report phase and second stage access selection phases~~ and go to the next stage as indicated by RS network entry optimization TLV in the RNG-RSP message.

GroupResolution**Decision of Group:** Principle

Change as at page 108, line 43:

If the measurement is not required, after registration RS shall ~~directly go to the RS configuration phase skipping the neighbor station measurement report phase and second stage access selection phases~~ and go to the next stage as indicated by RS network entry optimization TLV in the RNG-RSP or REG-RSP message.

Reason for Group's Decision/Resolution

Adding the correct reference

Group's Notes**Editor's Notes****Editor's Actions** a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # B30004

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial

Part of Dis Satisfied

Page 121 Line 47

Fig/Table# 182

Subclause 6.3.10.3.1.1

Table caption should be moved to next page. Table numbering is not convenient.

Suggested Remedy

Insert a page break after Table 181c.

Table 182 should be Table 181d.

GroupResolution

Decision of Group: Principle

Insert a page break after Table 181c at page 122, line 47.

Table 182 should be Table 181d.

In addition,

(1) Replace "Table 182" by "Table 181d" in the entire document.

Reason for Group's Decision/Resolution

Additional correction

Group's Notes

Editor's Notes

Editor's Actions a) done

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07Comment # B30005Document under Review: P802.16j/D8Ballot ID: sb_16jR2

Comment Type Technical Part of Dis Satisfied Page 122 Line 31 Fig/Table# 181c Subclause 6.3.10.3.1.1

New MS indicator TLV is deleted from the text., we still refer to it in this table.
 Instead MR-BS informs the number of accepted new MSs in the RNG_RSP message.

Suggested Remedy

"Check availability to admit a RNG-RSP new MS entry. Then, send RNGRSP containing ~~New MS indicator~~ Number of accepted SSs TLV ~~and status with RS basic CID. Status=Success"~~

Page 122 Line 40:

"If RNG-REQ has ranging CID and MS MAC address, then RS ~~adds New MS Indicator and~~ relays it to BS with RS Basic CID"

Page 122, Line 42:

"Identify MS and its connecting RS. ~~Check the New MS Indicator, If the result is valid,~~
If MS is accepted, ~~S~~send RNG-RSP containing management CIDs with RS basic CID, otherwise, send RNG-RSP with abort status"

GroupResolutionDecision of Group: Principle

References of Page/Line are wrong.

at Page 123, Line 30,

"Check availability to admit a RNG-RSP new MS entry. Then, send RNGRSP containing ~~New MS indicator~~ Number of accepted SSs TLV ~~and status with RS basic CID. Status=Success"~~

at Page 123 Line 40:

"If RNG-REQ has ranging CID and MS MAC address, then RS ~~adds New MS Indicator and~~ relays it to BS with RS Basic CID"

at Page 123, Line 42:

"Identify MS and its connecting RS. ~~Check the New MS Indicator, If the result is valid,~~
If MS is accepted, ~~S~~send RNG-RSP containing management CIDs with RS basic CID, otherwise, send RNG-RSP with abort status"

Reason for Group's Decision/Resolution

Correcting the references

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # **B30006**

Document under Review: **P802.16j/D8**

Ballot ID: **sb_16jR2**

Comment Type Editorial Part of Dis Satisfied Page 122 Line 53 Fig/Table# 182a Subclause 6.3.10.3.1.1

Table caption not in good position

Suggested Remedy

Insert a page break after Table 182.
Renumber Tables 182x with 181y.

GroupResolution

Decision of Group: Principle

- (1) Insert a page break after Table 182 (now Table 181d).
- (2) Table 182a on p. 123 line 53 should be Table 181e.
- (3) Replace "Table 182a" by "Table 181e" in the entire document,

Reason for Group's Decision/Resolution

Clarification of what the editors need to do.

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30007

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 133 Line 1 Fig/Table# 103a Subclause 6.3.10.3.2.1

Figure caption not in good position

Suggested Remedy

Position the figure so that the figure and the caption falls on the same page.

GroupResolution

Decision of Group: Principle

Position the figure 102a so that the figure and the caption falls on the same page 134.

Reason for Group's Decision/Resolution

Clarification for the editors

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30008

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial

Part of Dis Satisfied

Page 45

Line 55

Fig/Table# 165c

Subclause 6.3.2.3.62

Bracket is missing.

Suggested Remedy

Change the row as:

If(Report Type == 0) ↓

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # B30009

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial

Part of Dis Satisfied

Page 173 Line 58

Fig/Table#

Subclause 6.3.28

"RS stations".

RS already means "Relay station"

Suggested Remedy

Change as:

"...MR-BS(s) or RS(s) stations,..."

GroupResolution

Decision of Group: Principle

Change as at page 174, line 58:

"...MR-BS(s) or RS(s) stations,..."

Reason for Group's Decision/Resolution

Reference as to where the change needs to be made

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # B30010

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 176 Line 50 Fig/Table# 155c Subclause 6.3.30

Figure 155c is not readable. Aspect ratio of the original image was not kept the same.

Suggested Remedy

Re-scale the original figure image with aspect ratio unchanged.

GroupResolution

Decision of Group: Principle

accept the proposed remedy at page 177, figure 154c.

Reason for Group's Decision/Resolution

Reference as to where the change needs to be made

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30011

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment

Type Editorial

Part of Dis

Satisfied

Page 186

Line 26

Fig/Table# 206a

Subclause 7.2.2.4.5

Is HMAC_KEY_SZD for DL or UL?

Suggested Remedy

Change usage text as:

"The key which is used for signing ~~U~~DL management messages."

GroupResolution

Decision of Group: Principle

page 187, line 26, adopt the proposed remedy

Reason for Group's Decision/Resolution

Reference as to where the change needs to be made

Group's Notes

Editor's Notes

Editor's Actions

a) done

Comment by:

Israfil Bahceci

Membership Status: NonmemberDate: 2009-01-07Comment # B30012Document under Review: P802.16j/D8Ballot ID: sb_16jR2

<u>Comment</u>	<u>Type</u> Editorial	<u>Part of Dis</u> <input type="checkbox"/>	<u>Satisfied</u> <input type="checkbox"/>	<u>Page</u> 200	<u>Line</u> 42	<u>Fig/Table#</u>	<u>Subclause</u> 8.4.4.7.3
----------------	-----------------------	---	---	-----------------	----------------	-------------------	----------------------------

Reference need to be updated.
also Lines 43, 44, 55 of Page 200, Line 51 of Page 201

Suggested Remedy

Replace 8.4.4.2 by 8.4.4.1

GroupResolutionDecision of Group: Principle

Change text in the section 8.4.4.8.3 Frame structure for STR mode on page 201 as follows

The second approach uses frame structure defined in 8.4.4.7.2 for the MR-BS frame and the RS frame, which allows coexisting with TTR RS. An example of a STR frame structure which allows coexisting with TTR RS is shown in Figure 234e. This frame structure can support more than two hop relaying by including a transmit DL and a receive UL relay zone on the second carrier, as shown in Figure 234e. If the RS is not supporting subordinate RSs then the DL and UL relay zones shown in Figure 234e may not be present.

The arrangement of signaling shall be the same as that described in 8.4.4.1 and 8.4.4.8.2 except that it is possible that the RS frame be configured such that the RS is both transmitting and receiving at the same time but transmission and reception of the RS shall not be used on the same carrier when the interference induced by the transmitter operating in STR mode causes a link adaptation degradation of the link performance related to the STR receiver.

Reason for Group's Decision/Resolution

Proposed remedy was not clear.

Group's NotesEditor's NotesEditor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30013

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial

Part of Dis Satisfied

Page 205 Line 23

Fig/Table#

Subclause 8.4.4.10.1

Reference update

Also lines 32, 43 and 49 of Page 205

Suggested Remedy

Replace 8.4.4.1 by 8.4.4.2

GroupResolution

Decision of Group: Disagree

concern was resolved during REV2 alignment.

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions b) none needed

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30014

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial

Part of Dis Satisfied

Page 205 Line 32

Fig/Table#

Subclause 8.4.4.10.2

Editorial issue

Suggested Remedy

Change the sentence as:

"If the MR-BS and TTR RS frame structures is the same as the BS frame structure defined in 8.4.4.1-, ~~T~~he relay link between the RS and its superordinate station shall operate in Group-2 H-FDD only, where the RS shall listen to DL Subframe 2 and transmit in uplink subframe UL2."

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Does not require the action from the editor. The proposed remedy of B30015 implies this proposed remedy.

Editor's Notes

Editor's Actions b) none needed

Taken care of by remedy to B30015

Comment by:

Israfil Bahceci

Membership Status: NonmemberDate: 2009-01-07Comment # B30015Document under Review: P802.16j/D8Ballot ID: sb_16jR2

Comment Type Technical Part of Dis Satisfied Page 205 Line 40 Fig/Table# Subclause 8.4.4.10.2

"When the MR-BS and TTR RS communicate each other by using the frame structures defined in 8.4.4.7.2,...."

In FDD and H-FDD mode, we have two DL/UL subframes (DL/UL subframe 1 & 2). For this second option, each sub frame may have relay zones as described in 8.4.4.7.2. This is not clear from the above statement.

Suggested Remedy

Change the text as:

"When the MR-BS and TTR RS communicate each other in Subframe 1 and Subframe 2 by using the frame structures defined in 8.4.4.7.2,...."

GroupResolutionDecision of Group: Principle

Change text in the section 8.4.4.11.2 Frame Structure for non-transparent TTR on page 206 as follows

The TTR RS may communicate with superordinate station in either H-FDD or full duplex FDD mode and it shall communicate with subordinate SSs operating in H-FDD mode only.

If the MR-BS and TTR RS frame structures is the same as the BS frame structure defined in 8.4.4.2, T the relay link between the TTR RS and its superordinate station shall operate in Group-2 H-FDD only, where the TTR RS shall listen to DL Subframe 2 and transmit in uplink subframe UL2. The access link between the RS and its subordinate SSs shall operate in Group-1 H-FDD mode only. The common SYNC symbol defined in 8.4.6.1.1.2 or R-amble defined in 8.4.6.1.1.3 may appear in the Group-2 DL Subframe of the superordinate station for the RS synchronization.

When the MR-BS and TTR RS communicate each other in Subframe 1 and Subframe 2 by using the frame structures defined in 8.4.4.7.2 (with the exception of preamble in Subframe 2), it may operate in either H-FDD or full duplex FDD. When operating in full duplex FDD, DL subframe and UL subframe of relay link may be overlapped. The access link between the RS and its subordinate SSs shall operate in H-FDD using the frame structure defined in 8.4.4.2.

Reason for Group's Decision/Resolution

Proposed remedy needed further work to make sure the entire section of text was corrected as per the comment

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30016

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial

Part of Dis Satisfied

Page 205 Line 19

Fig/Table#

Subclause 8.4.4.10.1

"When the MR-BS and transparent RS communicate each other by using the frame structures defined in 8.4.4.7.2,..."

The referred subclause defines frame structure for non-transparent RSs. It should either be 8.4.4.7.1, or 8.4.4.7 to cover coexistence of transparent and non transparent TTR relay.

Further more, the clause does not clearly explain how FDD subframes (defined in 8.4.4.2) will be in case of transparent frame structure. The intention is to mention that subframe 1 & 2 in H-FDD frame structure may contain transparent or UL relay zones.

Suggested Remedy

Change the text as:

"When the MR-BS and transparent RS communicate each other in Subframe 1 and Subframe 2 by using the frame structures defined in 8.4.4.7.2,..."

or

"When the MR-BS and transparent RS communicate each other in Subframe 1 and Subframe 2 by using the frame structures defined in 8.4.4.7.12,..."

GroupResolution

Decision of Group: Principle

When the MR-BS and transparent RS communicate each other in Subframe 1 and Subframe 2 by using the frame structures defined in 8.4.4.7-28.1, it may operate in either H-FDD or full duplex FDD. When operating in full duplex FDD, DL subframe and UL subframe of relay link may be overlapped. The access link between the RS and its subordinate SSs shall operate in H-FDD mode according to the frame structure described in 8.4.4.2-~~However,~~ with exception that DL subframe in the access link shall only contain transparent zone in DL or access zone in UL (i.e. DL subframe shall exclude the preamble and MAP transmission).

Reason for Group's Decision/Resolution

Proposed remedy needed further work to make sure the entire section of text was corrected as per the comment

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # **B30017**

Document under Review: **P802.16j/D8**

Ballot ID: **sb_16jR2**

Comment Type Editorial

Part of Dis Satisfied

Page 226 Line 28

Fig/Table# 460g

Subclause 8.4.5.10.5

Typo

Suggested Remedy

"No. of subvchannel"

GroupResolution

Decision of Group: Principle

"No. of subvchannel" at page 226 figure 475g.

Reason for Group's Decision/Resolution

Reference as to where the change needs to be made

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30018

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 210 Line 1 Fig/Table# Subclause 8.4.5.3.31

Redundant. The subclause is moved to R-MAP IE section. Also is 8.4.5.4.34.

Suggested Remedy

Remove 8.4.5.3.31

Remove 8.4.5.4.34

GroupResolution

Decision of Group: Disagree

We need to keep those IEs because of different formats at normal IE and R-MAP IE.

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions b) none needed

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # B30019

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Technical Part of Dis Satisfied Page 231 Line 17 Fig/Table# 460I Subclause 8.4.5.10.10

Tunnel CID can not be reduced CID. Only basic or multicast CIDs can be reduced according to 8.4.5.3.20.1

This notion may also appear elsewhere in the text and may need to be corrected wherever it causes confusion.

Suggested Remedy

Change Line 17 and Line 25 of Page 231 as:

~~CIDRCID_E()~~

GroupResolution

Decision of Group: Principle

Change Line 17 and Line 25 in Table 475I of Page 231 as:

| ~~CIDRCID_E()~~ | ~~16variable~~ |

Reason for Group's Decision/Resolution

Commenter missed part of the required fix.

Group's Notes

Editor's Notes

Editor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07

Comment # B30020

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Editorial Part of Dis Satisfied Page 240 Line 1 Fig/Table# Subclause 8.4.9.4.3.3

Equations 141a and 141b malformed.

Suggested Remedy

Rewrite/reformat the equations.

GroupResolution

Decision of Group: Principle

change the equation 141a, 141b to start with Re and Im as following :

Re...

Im...

Reason for Group's Decision/Resolution

Clarification on what the editors need to do.

Group's Notes

Editor's Notes

Editor's Actions

a) done

Comment by:

Israfil Bahceci

Membership Status:

Nonmember

Date: 2009-01-07Comment # B30021Document under Review: P802.16j/D8Ballot ID: sb_16jR2Comment Type EditorialPart of Dis Satisfied Page 275 Line 37Fig/Table#Subclause 11.25.1

Frame configuration TLVs are moved to RS Config CMD message.

Suggested Remedy

Do the following modifications:

Page 275, Line 37:

"When Bit#12 is set to 0, the MR-BS configures the frame configuration of the RS using the Frame configuration TLV in RS Config CMD RGD. When Bit#12 is set to 1, the MR-BS provides the frame configuration of the superordiante station using Frame configuration TLV in RS Config CMD RGD. Bit#12 can be set to '1' only when STR relay."

Page 283, Line 19:

This field is used by an MR-BS to inform usage of the frame structure to all RSs (see also Bit #1~~2~~3 of RS operational mode TLV in subclause 11.25.1).

Page 287, Line 3:

This field is used by an MR-BS to inform the usage of the direct relay zone to all RSs (see also Bit #1~~2~~3 of RS operational mode TLV in subclause 11.25.1).

Page 280, Line 25:

Bit 0: set to 1, it indicates that the RS shall use the RGD RS Config CMD message to obtain frame configuration.

|

GroupResolutionDecision of Group: Principle

Do the following modifications:

Page 276, Line 37:

"When Bit#12 is set to 0, the MR-BS configures the frame configuration of the RS using the Frame configuration TLV in RS Config CMD RGD. When Bit#12 is set to 1, the MR-BS provides the frame configuration of the superordiante station using Frame configuration TLV in RS Config CMD RGD. Bit#12 can be set to '1' only when STR relay."

Page 284, Line 19:

This field is used by an MR-BS to inform usage of the frame structure to all RSs (see also Bit #12~~3~~ of RS operational mode TLV in subclause 11.25.1).

Page 288, Line 3:

This field is used by an MR-BS to inform the usage of the direct relay zone to all RSs (see also Bit #12~~3~~ of RS operational mode TLV in subclause 11.25.1).

Page 281, Line 25:

Bit 0: set to 1, it indicates that the RS shall use the RGD RS Config CMD message to obtain frame configuration.
If

Reason for Group's Decision/Resolution

Correcting the references as to where the changes need to be made.

Group's Notes

Editor's Notes

Editor's Actions a) done

Comment by:

Israfil Bahceci

Membership Status: NonmemberDate: 2009-01-07Comment # B30022Document under Review: P802.16j/D8Ballot ID: sb_16jR2Comment Type Technical Part of Dis Satisfied Page 40 Line 1 Fig/Table# Subclause 6.3.2.3.60

"In distributed scheduling mode, the MR-BS and scheduling RS shall individually construct the RCD message that relates to the relay, link that they control and scheduling RSs shall use information provided to them in the RS_Config-CMD message in order to construct the message with the necessary TLVs."

In distributed scheduling, the relay link profile may be also prepared by the scheduling RS.

Suggested Remedy

Replace "shall" by "may":

"In distributed scheduling mode, the MR-BS and scheduling RS shall individually construct the RCD message that relates to the relay link that they control and scheduling RSs ~~shall~~ **may** use information provided to them in the RS_Config-CMD message in order to construct the message with the necessary TLVs."

GroupResolutionDecision of Group: AgreeReason for Group's Decision/ResolutionGroup's NotesEditor's NotesEditor's Actions a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Israfil Bahceci

Membership Status: Nonmember

Date: 2009-01-07

Comment # B30023

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment Type Technical Part of Dis Satisfied Page 66 Line 56 Fig/Table# 165t Subclause 6.3.2.3.77

The reason for Basic CID flag can be used to inform association of transport CID with the basic CID in case it is needed.
The if else statement is not accurate for this case.

Suggested Remedy

Remove "else {" text as indicated:

Page 66, Line 56: Remove else

} else{

Page 67, Line 7: Remove the closing bracket

}

Page 67, Line 19: Remove else

} else{

Page 67, Line 25: Remove the closing bracket

}

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done

Comment by:

Avner Aloush

Membership Status: Nonmember**Date:** 2009/01/14**Comment #** B30024L**Document under Review:** P802.16j/D8**Ballot ID:** sb_16jR2**Comment** **Type** Technical **Part of Dis** **Satisfied** **Page** 115 **Line** 34 **Fig/Table#** **Subclause** 6.3.7.7

Discuss and adopt the proposed remedy for refinement.

Suggested Remedy

Section 6.3.7.7

Insert the sentence at the end of paragraph of the section

"The format of R-MAP message is defined at section 8.4.5.10."

Page 115 line 34

Frame configuration during operational mode may be done either in a quasi-static manner(default mode) using RCD and RS_Config-CMD messages (See 6.3.2.3.60 and 6.3.2.3.64), or in a dynamic manner using R-FCH (See 8.4.4.7.4~~8~~).

Page 36 line 33-35

The following parameter shall be included in the Basic Capability Request if the SS or RS is intended to solicit NSP information

Page 109

Section 6.3.9.9.2

Add the text as following :

When an RS performs registration, MR-BSs and RSs shall follow the same steps as specified in subclause 6.3.9.9 with the modification described in Figures 85a, b.

Once the RS has sent a REG-REQ to the MR-BS, it shall wait for a REG-RSP. Figure 85a shows the waiting procedure that shall be followed by the RS.**GroupResolution****Decision of Group:** Agree**Reason for Group's Decision/Resolution****Group's Notes****Editor's Notes****Editor's Actions** a) done

2009/09/06

IEEE 802.16-09/0001r3

Comment by:

Avner Aloush

Membership Status:

Nonmember

Date:

2009/01/15

Comment # B30025L

Document under Review: P802.16j/D8

Ballot ID: sb_16jR2

Comment

Type Editorial

Part of Dis

Satisfied

Page 200

Line 58

Fig/Table#

Subclause

Discuss and adopt the proposed remedy for refinement.

Suggested Remedy

Page 200 line 58

Not clear text:

A relay zone may be utilized for either transmission, or reception, or idle but the RS shall not be required to support both transceiver modes ~~of operation~~ within the same zone.

Page 201 line 8

Delete line 8

~~Each RS frame begins with a preamble followed by an FCH and the DL-MAP and possibly a UL-MAP.~~

It is already written in page 200

Page 284 line 26

Number of frames

Page 284 Line 48

Zone ~~Frame Configuration~~ Duration (unsigned 5-bit)

It is the zone duration and not the frame duration. It is misleading.

Page 285 Line 15

Zone ~~Frame Configuration~~ Duration

Page 201 line 4

The contents of the FCH, DL-MAP and UL-MAP in the access zone transmitted by the RS may or may not be the same as ~~may be different from~~ those transmitted in the access zone by the MR-BS.

GroupResolution

Decision of Group: Agree

Reason for Group's Decision/Resolution

Group's Notes

Editor's Notes

Editor's Actions a) done